

HEX-O-MAGNETIC PEN KIT INSTRUCTIONS



Supplies Needed:
10.5 mm drill bit
Hex-O-Magnetic bushings

We assume you already know how to turn a pen on a lathe. If not refer to our “Pen turning 101” instruction sheet you can download from our web site.
www.penkits.biz

Drill your blank with a 10.5 mm drill bit and prep as usual for turning. Turn the blank using the bushings for this kit. After deciding which end you want for the tip, press the tip in.

Now press the finial cap into the other end. Un-screw the tip and put the spring into the pen barrel (large end in first, small end will press against the refill) Slide in the refill and screw on the tip.

The Cap with the clip is magnetic, and can be posted on the either end of the pen.

Note: You can use “Waterman Refills” and the ever popular “Pilot G2 Refills” for this kit as easy replacements available at all office supply stores.